	Туре	Hits	Search Text
1	IS&R	155	(369/44.16).CCLS.
2	BRS	2095	focus\$3 near2 coil
3	BRS	86	((369/44.16).CCLS.) and (focus\$3 near2 coil)
4	BRS	7583	optical near pickup and focus\$3
5	BRS	10265	lens near holder
6	BRS	603	(optical near pickup and focus\$3) and (lens near holder)
7	BRS	4343	focus\$3 near coil
8	BRS	343	((optical near pickup and focus\$3) and (lens near holder)) and (focus\$3 near coil)

	DBs	Time Stamp	Comments	Error Definition
1	USPAT	2003/06/10 16:58		
2	USPAT	2003/06/10 16:59		
3	USPAT	2003/06/10 17:39		
4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/10 18:39		
5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/10 18:40		
6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/11 11:33		
7	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/10 18:44		
8	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/11 11:32		

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L9	343	((optical near pickup and focus\$3) and (lens near holder)) and (focus\$3 near coil)	USPAT; US-PGP UB; EPO; JPO; DERWEN T; IBM_TD B	2003/06/11 11:33
2	BRS	L10	603	, , , , , , , , , , , , , , , , , , ,	USPAT; US-PGP UB; EPO; JPO; DERWEN T; IBM_TD B	2003/06/11 11:34
3	BRS	L11	260	10 not 9	USPAT; US-PGP UB; EPO; JPO; DERWEN T; IBM_TD B	2003/06/11 11:34